

<b>Project No.</b>	<b>Client</b>	<b>Location</b>	<b>Boring No.</b>	<b>Monitoring Well No.</b>	<b>Date</b>
00445	Beacon Bay Auto Wash	481 E. 17 <sup>th</sup> St., Costa Mesa	CB1		August 3, 2005
<b>PID</b>	<b>BLOWS/ft. Sampler</b>	<b>DEPTH in feet</b>	<b>USCS Designation &amp; Soil Type</b>	<b>Color</b>	<b>Secondary Characteristics</b>
0	8-15-16	<b>5</b>	Silty Clay (CL)	Dark Brown	Semi-Stiff, Sl Moist, No Odor
0	16-22-26	<b>10</b>	Silty Sands (SM)	Tan	Loose, Dry, No Odor
0	16-22-29	<b>15</b>		Light Brown	Medium Dense
0	12-14-16	<b>20</b>		Brown	Loose, Very Moist
0	7-11-19	<b>25</b>			Wet
0	7-13-16	<b>30</b>	Silty Clay (CL)	Light Brown	Stiff, Wet, No Odor
0	12-14-19	<b>35</b>		Tan	
<b>Field Engineer</b>	<b>Drilling Contractor</b>	<b>Drilling Foreman</b>	Boring terminated at 35'. Groundwater encountered at 16-17'. Boring backfilled with soil from boring. Overflow soil drummed and manifested.		
M. Anselmo	J & H - Hollow Stem	Conrad			